

Inspection Photos

Location Name: Bunn I 35-25

API #: 05-123-23193

Location ID: 305581



Wellhead looking south. Has previous operator's emergency contact information posted. Needs to be removed and/or replaced



Trash at location entrance and perimeter of location needs to be removed



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Bunn I 35-25

API #: 05-123-23193

Location ID: 305581



Battery looking south



2" Balon bypass valve at separator header appears to be leaking by, frozen over



Inspection Photos

Location Name: Bunn I 35-25

API #: 05-123-23193

Location ID: 305581



Wellhead looking south. Has previous operator's emergency contact information posted. Needs to be removed and/or replaced



Weeds along west edge of location needs to be controlled



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources