

Inspection Photos
Location Name: Bunn 1-35
API #: 05-123-10978
Location ID: 319270



Wellhead looking west



Stained soil around wellhead needs to be cleaned up. Appears that wellhead packing is leaking or has leaked at some point