

Photo#1:  
Location 10/4/17



Photo#2:  
Location 10/25/17



October 25, 2017

Photo#3:

Area of Concern off Access Road has been Resolved

10/4/17



Photo#4:

10/25/17



October 25, 2017

Photo#5:

10/4/17



Perimeter Controls have been installed.

Photo#6:

10/25/17



October 25, 2017

Photo#7:

10/4/17



Perimeter Controls have been installed.

Photo#8:

10/25/17



October 25, 2017

Photo#9:

10/4/17



Perimeter Controls have been installed.

Photo#10:

10/25/17



October 25, 2017



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Sandridge Beaver Creek Loc#451938

Photo#11:

Wattles in areas are not properly installed; not seated in.



October 25, 2017