

Inspection Photos

11/1/2017

Operator: DIAMOND OPERATING, INC. - 24320

Location ID: 317281

Inspection Doc. Number: 682502765

Washington County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the southeast corner of the tank battery facility. Photo shows signs.



Photo 2: Photo taken from the east side of the produced water tank. Photo shows produced water is being discharged via the overflow-siphon line and into the containment berm.



Photo 3: Photo taken from the east side of the produced water tank. Photo shows produced water is being discharged via the overflow-siphon line and into the containment berm.

Inspection Photos
Operator: DIAMOND OPERATING, INC. - 24320
Location ID: 317281



Photo 4: Photo taken from the north end of the produced water tank. Photo shows a leak occurring at the base of the manifold. This will require repair.



Photo 5: Photo taken from the north end of the produced water tank. Photo shows a leak occurring at the base of the manifold. This will require repair.

Inspection Photos
Operator: DIAMOND OPERATING, INC. - 24320
Location ID: 317281



Photo 6: Photo taken from the west end of the battery. Photo shows produced water discharged into the containment berm. Photo also shows oil residue.



Photo 7: Photo taken from the west end of the battery. Photo shows produced water discharged into the containment berm. Photo also shows oil residue.



Photo 8: Photo taken from the east side of the produced water tank. Inspector met with pumper on site. Pumper was able to shut in the wells and stop the discharge. Photo shows discharge has been stopped.