

Inspection Photos
Well Name: Federal 11-90-24 1
Location ID: 324469



Photo 1. Unused equipment near separator.



Photo 2. No label on chemical container.

Inspection Photos
Well Name: Federal 11-90-24 1
Location ID: 324469



Photo 3. Staining at wellhead.



Photo 4. Staining at pumpjack.