

Inspection Photos  
Well Name: Federal 11-90-35 #1  
Location ID: 324471



Photo 1. Well has been disconnected.



Photo 2. No capacity on produced water tanks.

Inspection Photos  
Well Name: Federal 11-90-35 #1  
Location ID: 324471



Photo 3. Staining around and under unused tanks.



Photo 4. Staining around and under unused tanks.



Inspection Photos  
Well Name: Federal 11-90-35 #1  
Location ID: 324471



Photo 5. Unused tanks and manifold.



Photo 6. Unused tanks

Inspection Photos  
Well Name: Federal 11-90-35 #1  
Location ID: 324471



Photo 7. Hatches open on stored tanks.



Photo 8. Unused tank.