



**Photo 1. View of the project area from the northeastern corner facing center. Revegetation is progressing in areas not being used for production.**



**Photo 2. View of the northern portion of the project area from the northeastern corner facing westward. Revegetation is largely comprised of species such as western wheatgrass (*Pascopyrum smithii*), brome grass (*Bromus* sp.), and vetch (*Astragalus* sp.)**



**Photo 3. View of the southern portion of the project area from the southeastern corner facing westward.**



**Photo 4. View of view of musk thistles (*Carduus nutans*) that have flowered and are senescing in the southwestward portion of the project area.**



**Photo 5. View of Canada thistles in the northern portion of the project area.**



**Photo 6. View of debris stored in the southern portion of the project area that needs to be removed.**



**Photo 7. View of silt trap in good condition in the southern portion of the project area.**