

Inspection Photos
Location Name: Elk Springs Unit 4
API: 05-081-06837



Photo 1. Overview of location taken at entrance facing northeast. Flowline work visible on right of frame beginning at wellhead.