

Inspection Photos

10/30/2017

Operator: SAND HILLS SOCIETY - 76120

Location ID: 403660

Inspection Doc. Number: 682502768

Washington County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: SAND HILLS SOCIETY - 76120
Location ID: 403660



Photo 1: Photo taken from the well location. Photo shows well location remains predominantly unvegetated. Unable to find evidence that reclamation activities have been conducted.



Photo 2: Photo taken from the southeast end of the well location, facing northwest. Photo shows well location remains predominantly unvegetated, and pit remains open. Unable to find evidence that reclamation activities have been conducted.

Inspection Photos
Operator: SAND HILLS SOCIETY - 76120
Location ID: 403660



Photo 3: Photo taken from the southeast end of the pit location, facing north. Photo shows pit remains open and pipe remain.



Photo 4: Photo taken from the east end of the pit location, facing west. Photo shows pit remains open and pipe remain.