

Inspection Photos
Location Name: McCallum Unit 51
API: 05-057-06032



Photo 1. Overview of location taken at entrance facing southeast.



Photo 2. Stained soil at wellhead.