

- Huskey “B” Unit 1
- 05-033-06008




Photo 1: Wellhead sign. Previous inspection.

- Huskey “B” Unit 1
- 05-033-06008



Photo 2: Wellhead sign. Follow-up inspection.

- Huskey “B” Unit 1
- 05-033-06008



**Photo 3: Recirculating line at oil tank battery. Previous inspection.**

- Huskey “B” Unit 1
- 05-033-06008



**Photo 4: Locked and tagged out lines at recirculating pump. Follow-up inspection.**

- Huskey “B” Unit 1
- 05-033-06008



Photo 5: Close up of recirculating line. Previous inspection.

- Huskey “B” Unit 1
- 05-033-06008



Photo 6: Locked out and tagged out recirculating lines at oil tank battery. Follow-up inspection.

- Huskey “B” Unit 1
- 05-033-06008



**Photo 7: Locked out tagged out lines at dog leg by gas meter run. Follow-up inspection.**

- Huskey “B” Unit 1
- 05-033-06008



**Photo 8: Locked out and tagged out lines at production tank. Follow-up inspection.**

- Huskey “B” Unit 1
- 05-033-06008



Photo 9: Location overview. Follow-up inspection.

- Huskey “B” Unit 1
- 05-033-06008



Photo 10: Location overview. Follow-up inspection.