

- Chevillar 32 - 32
- 05-067-09196



Photo 1: Wellhead sign. Previous inspection.

- Chevillar 32 - 32
- 05-067-09196



Photo 2: Wellhead sign. Follow-up inspection.

- Chevillar 32 - 32
- 05-067-09196



Photo 3: Weeds around wellhead. Previous inspection.

- Chevillar 32 - 32
- 05-067-09196



Photo 4: Cleaned up weeds around wellhead. Follow-up inspection.

- Chevillar 32 - 32
- 05-067-09196



Photo 5: Produced water tank with peeling NFPA label and no capacity label. Previous inspection.

- Chevillar 32 - 32
- 05-067-09196



Photo 6: Labeled produced water tank. Follow-up inspection.

- Chevillar 32 - 32
- 05-067-09196



Photo 7: Unused equipment and debris on left side of pump jack. Previous inspection.

- Chevillar 32 - 32
- 05-067-09196



Photo 8: Removed unused equipment at wellhead. Follow-up inspection.

- Chevillar 32 - 32
- 05-067-09196



Photo 9: Concrete cribbing in corner of location. Previous inspection.

- Chevillar 32 - 32
- 05-067-09196



Photo 10: Removed concrete cribbing and debris. Follow-up inspection.

- Chevillar 32 - 32
- 05-067-09196



Photo 11: View of weeds covering location. Previous inspection.

- Chevillar 32 - 32
- 05-067-09196



Photo 12: Removed weeds and marked deadman. Follow-up inspection.

- Chevillar 32 - 32
- 05-067-09196



Photo 13: Weeds growing in and on production tank battery berms from backside. Previous inspection.

- Chevillar 32 - 32
- 05-067-09196



Photo 14: Removed weeds and repaired berms. Follow-up inspection.

- Chevillar 32 - 32
- 05-067-09196



Photo 15: Location overview. Follow-up inspection.

- Chevillar 32 - 32
- 05-067-09196



Photo 16: Location overview. Follow-up inspection.