

# Final Reclamation Inspection

November 2, 2017

Operator: SUNDANCE ENERGY INC - 10340

Location ID: 429637

Weld County, CO

NENW Section 16 T4N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

**Inspection Photos**  
**Location Name: Sundance Beneficial Reuse Area**  
**Location ID: 429637**




**Photo 1.** Photo taken on November 2, 2017 from the south central BRA, facing East. Wheat stubble from the 2016 harvest appeared to have uniform establishment and density reflective of reference crop area levels, indicating the BRA has met Rule 1004 standards. See photo 2 illustrating a reference area.



**Photo 2.** Reference photo taken on November 2, 2017 from the wheat field southwest of the BRA, facing West. Wheat stubble in reference crop areas appear to be reflective of the BRA, indicating the BRA has met Rule 1004 standards.

Inspection Photos  
Location Name: Sundance Beneficial Reuse Area  
Location ID: 429637



**Photo 3.** Photo taken on June 2, 2016 by COGCC staff from 40.315553, -104.898414, facing North. The photo illustrates the western half of the Sundance Beneficial Reuse Area (BRA) which is the northernmost wheat field. Based off this photo, it appears the BRA was reflective of reference crop area levels, indicating the BRA has met Rule 1004 standards.



Inspection Photos  
Location Name: Sundance Beneficial Reuse Area  
Location ID: 429637



**Photo 4.** Photo taken on June 2, 2016 by COGCC staff from the previously mentioned coordinates, facing Northeast. The photo illustrates the eastern half of the Sundance Beneficial Reuse Area (BRA) which is the northernmost wheat field. Based off this photo, it appears the BRA was reflective of reference crop area levels, indicating the BRA has met Rule 1004 standards.