

Photo#1:
Overview of Location from Entry to South West.



November 3, 2017

Photo#2:

Materials stored with no protection from Moisture or Containment have become Debris

6/2/16



Photo#3:

11/3/17



November 3, 2017

Photo#4:

Storage Units and Equipment stored at site had doors open and unsecured, which could entrap Wildlife.




Photo#5:



November 3, 2017

Photo#6:

Supplies are not organized in a Workman like Manner; insert is of Can of Adhesive



Photo#7:



November 3, 2017

Photo#8:

Photo from 5/8/14 Inspection of Concrete Cellar with 15 Conductors Set.



May 8, 2014



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Cascade Loc#424970

Photo#9:

Photo of Conductor area from 11/14/16 Inspection
Arrow indicates area where Conductors were buried



Photo#10:

Same area as in Photo#9 taken 11/3/17
Cellar & conductors have been excavated



Photo#1: There is no evidence of the AL Wells on this Active Location.

November 3, 2017

Photo#11:

Five of the Conductor lids are off



Photo#12:

Gate Panel of Cellar Fence is ajar



November 3, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Cascade Loc#424970

Photo#13:

Material excavated from Cellar stored at South end of Conductor installation.



November 3, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Cascade Loc#424970

Photo#14:

View of Location Fill Slope from Entry Road to South West.



November 3, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Cascade Loc#424970

Photo#15:

View from top at approximate middle of Fill Slope of Unstabilized Fill slope Material rattling, migrating down slope.



November 3, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Cascade Loc#424970

Photo#16:

View from bottom of Fill Slope to top, showing unstabilized conditions and lack of Vegetation..



November 3, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Cascade Loc#424970