

Inspection Photos

11/09/2017

Operator: GRAND MESA OPERATING CO - 35080

Location ID: 452771

Inspection Doc. Number: 682502779

Lincoln County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: GRAND MESA OPERATING CO - 35080
Location ID: 452771



Photo 1: Photo taken from the southeast end of the location, facing north. Operator installed surface roughening as a stormwater and sediment control BMP around the perimeter of the location. BMP had been installed prior to construction activities.



Photo 2: Photo taken from the southeast end of the location, facing west. Operator installed surface roughening as a stormwater and sediment control BMP around the perimeter of the location. BMP had been installed prior to construction activities.

Inspection Photos
Operator: GRAND MESA OPERATING CO - 35080
Location ID: 452771



Photo 3: Photo taken from the north end of the location. Photo shows topsoil salvage and stabilization in process.



Photo 4: Photo taken from the north end of the location, facing west. Photo shows topsoil salvage and stabilization in process.