

Inspection Photos
Location Name: Ocoma B #29-13
API: 05-123-13354



Photo 1: Wellhead, looking E. No operator, emergency # at wellhead.



Photo 2: Location, looking SE

Inspection Photos
Location Name: Ocoma B #29-13
API: 05-123-13354



Photo from J Gomez's prior inspection for comparison



Photo 3: Fence repaired

Inspection Photos
Location Name: Ocoma B #29-13
API: 05-123-13354



Photo from J Gomez's prior inspection for comparison



Photo 4: Leak repaired, stained soil removed