

Photo#1:

View of Location from Entry to West. The Built Location with one AL Well has not been Reclaimed.



November 3, 2017

Photo#2:

View over Location to North. Final Reclamation has not been performed



November 3, 2017



### Photo#3:

Valve Housing Located at NE Corner of Filled Pit. Insert is of Sign leaned up on Housing.



November 3, 2017



Photo#4:

View along Fill slope to East.



November 3, 2017