

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401452990

Date Received:

11/08/2017

FIR RESOLUTION FORM

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 74165

Name of Operator: RENEGADE OIL & GAS COMPANY LLC

Address: 6155 S MAIN STREET #210

City: AURORA State: CO Zip: 80016

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Espinosa, Bill

(303) 829-4982

billespinosa30@yahoo.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 681700865

Inspection Date: 09/07/2017

FIR Submit Date: 09/07/2017

FIR Status: _____

Inspected Operator Information:

Company Name: RENEGADE OIL & GAS COMPANY LLC

Company Number: 74165

Address: 6155 S MAIN STREET #210

City: AURORA State: CO Zip: 80016

LOCATION - Location ID: 413721

Location Name: PAR STATE 28-14 Number: 2 County: ARAPAHOE

Qtrqtr: SESW Sec: 28 Twp: 5s Range: 64w Meridian: 6

Latitude: 39.581460 Longitude: -104.559850

FACILITY - API Number: 05-005-00 Facility ID: 412570

Facility Name: Par State 28-14 Number: #2

Qtrqtr: SESW Sec: 28 Twp: 5s Range: 64w Meridian: 6

Latitude: 39.581460 Longitude: -104.559850

CORRECTIVE ACTIONS:

1 ☒ CA# 98215

Corrective Action: Remove and properly dispose of oily waste, per Rule 907.e.

Date: 09/15/2017

Response: CA COMPLETED

Date of Completion: 10/09/2017

Operator Comment: CA completed

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 98216

Corrective Action: Remove and properly dispose of oily waste, per Rule 907.e.

Date: 09/15/2017

Response: CA COMPLETED

Date of Completion: 10/09/2017

Operator
Comment: CA completed

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

3 ☒ CA# 98217

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 10/07/2017

Response: CA COMPLETED

Date of Completion: 10/09/2017

Operator
Comment: CA completed

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

4 ☒ CA# 98218

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 10/07/2017

Response: CA COMPLETED

Date of Completion: 10/09/2017

Operator
Comment: CA completed

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: CA completed

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Bill Espinosa

Signed:

Title: field supervisor

Date: 11/8/2017 8:57:23 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401452990	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files