

Inspection Photos
Location Name: Hume 1-29
API: 05-009-06555



1. Location north looking south 7/26/2017



2. Pumping unit & VGS covered with vegetation 7/26/2017

Inspection Photos
Location Name: Hume 1-29
API: 05-009-06555



3. Pumping unit & VGS covered with vegetation 7/26/2017



4. Water tank without Berms and Labeling 7/26/2017

Inspection Photos
Location Name: Hume 1-29
API: 05-009-06555



5. Inadequate wildlife netting