

Inspection Photos
Location Name: Catamount IGE #139
API: 05-067-09534



300 bbl. PW AST with earthen berm.



Load out valve leaking during field inspection.

Inspection Photos
Location Name: Catamount IGE #139
API: 05-067-09534



Fluids in containment area.



Gooseneck trailer parked on location.