

Inspection Photos

11/14/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 329000

Inspection Doc. Number: 682502803

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the well location, facing north. Previous inspection required operator to perform additional reclamation at the well location. Photo shows location remains predominantly unvegetated and exposed soil. Unable to find evidence that additional reclamation activities have been conducted per the corrective actions.



Photo 2: Photo taken from the well location, facing northeast. See comments under photo 1



Photo 3: Photo taken from the north end of the location, facing southeast. See comments under photo 1



Photo 4: Photo taken from the north end of the location, facing south. See comments under photo 1



Photo 5: Photo shows vegetation over the adjacent reference area. Photo shows disturbance area is not reflective of the reference.



Photo 6: Photo taken from the south end of the former battery facilities location, facing northwest. Photo shows battery location has not been reclaimed to its designated final land use. No 502.b variance to not reclaim the location has been submitted or approved by the operator.



Photo 7: : Photo taken from the south end of the former battery facilities location, facing north. See comments under photo 6.