

Photo#1:

Overview of Location from entry to South West. Insert is of sign installed at South East corner of Pit.



November 3, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Cascade Creek Loc#335902

Photo#2:

View of Pit from South East end of Pit to North West.



November 3, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Cascade Creek Loc#335902

Photo3:

View of Fencing along North Pit perimeter, to West.



November 3, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Cascade Creek Loc#335902

Photo#4:

Mobil Pump Equipment at South side of Pit



Photo#5:

Hosing from Pump is laying over Pit fence panels



November 3, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Cascade Creek Loc#335902

Photo#6:
View of Fencing along West end of Pit.



Photo#7:
View of Fencing along North Pit perimeter to East



November 3, 2017

Photo#8:
View along Fill slope to East



November 3, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Cascade Creek Loc#335902