

Photo#1:

Overview of Location from Access Road to South East.



November 15, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Chevron SKR Loc#324443

Photo#2:

View over Location from top of NE Cut Slope to SW Cut Slope.



November 15, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Chevron SKR Loc#324443

Photo#3:

C List Weed, Mullein is forming dense stands. B list Weeds, Houndstongue and Thistle were also noted on Location.



Photo#4:



November 15, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Chevron SKR Loc#324443