

EASTCO Operating LLC, Vermillion 1  
039-06682

Inspection #688300652

11/16/2017

Routine Inspection

Sign at CR 173



11.16.2017



Pumper 7197400790

**EastCo Operating, LLC**

**Vermillion #1**

**API No. 05-039-06682-00**

**SW4/NE4 Sec 2-T13S-R58W**

**Elbert County**

**County Road 26 & 173**

11.16.2017





11.16.2017















11.16.2017



500

26729



11.16.2017



DO NOT ENTER

THIS TANK MAY CONTAIN  
FATAL VAPORS



NO ENTRE  
ESTE TANQUE CONTIENE  
VAPORES VENENOSOS

CRUDE OIL



TK001-01 OIL

11.16.2017



Drill pit



11.16.2017



Double layer of berms  
at low side of location



11.16.2017



Ditch on south side of location



11.16.2017