

Inspection Photos
Well Name: Badger Wash Federal 1-32
Location ID: 312478



Photo 1. Location covered in weeds.



Photo 2. Weeds identified as Halogeton, a Class C noxious weed.

Inspection Photos
Well Name: Badger Wash Federal 1-32
Location ID: 312478



Photo 3. Tank containment with weeds, debris and animal holes in it.



Photo 4. Produced water tank with incomplete signage.