

Photo#1:  
View North over Location Center



Photo#2:  
View South over Location Center



October 30, 2017

Photo#3:  
View East over Location Center



Photo#4:  
View West over Location Center



October 30, 2017



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: XOG Wells Loc#312540

Photo#5:

Knapweed



Noxious Weeds, B List Knapweed & C List Halogeton were noted on site.

Photo#6:

Halogeton; circled in red.



October 30, 2017



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: XOG Wells Loc#312540