

Photo#1:

View North over Location Center



Photo#2:

View South over Location Center

Note debris weeds within 25Ft of Well Head area.



October 30, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: XOG Alstatt Loc#312444

Photo#3:
View East over Location Center



Photo#4:
View West over Location Center



October 30, 2017

Photo#5:
Knapweed on Location



Photo#6:
Unmarked Anchor indicated by arrow.



October 30, 2017