

Inspection Photos

11/20/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 327102

Inspection Doc. Number: 682502879

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the southeast corner of the former battery location, facing west. Previous inspections required operator to perform additional reclamation activities on the well and battery location. Unable to find evidence that additional reclamation has been conducted.



Photo 2: Photo taken from the southeast corner of the former battery location, facing north. Previous inspections required operator to perform additional reclamation activities on the well and battery location. Unable to find evidence that additional reclamation has been conducted.



Photo 3: Photo taken from the well location. Photo shows crop has been removed from the well location.