

# Inspection Photos

11/20/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 424046

Inspection Doc. Number: 682502883

Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC



**Photo 1:** Photo taken from the west end of battery location. Inspection #682502655 required operator to remove riser. Photo shows riser has not been removed per 1004.a