

Inspection Photos

11/20/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 326853

Inspection Doc. Number: 682502885

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the area of the well and access road, facing north. Sundry doc. #401459517 indicated operator will address concerns from previous corrective actions once crop is harvested. Photo shows corn crop has been harvested, unable to find evidence that additional reclamation activities have been conducted.



Photo 2: Photo taken from the area of the well and access road, facing east. See comments under photo 1.



Photo 3: Photo taken from the area of the well and access road, facing south. See comments under photo 1.



Photo 4: Photo taken from the area of the well and access road, facing west. See comments under photo 1.