

# Inspection Photos

11/20/2017

Operator: FOUNTAINHEAD RESOURCES LTD -  
30658

Location ID: 322701

Inspection Doc. Number: 682502889  
Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: FOUNTAINHEAD RESOURCES LTD - 30658  
Location ID: 322701



**Photo 1:** Photo taken from the well location, facing east. Previous inspection required operator to perform additional reclamation activities. Unable to find evidence that additional reclamation has been conducted. Green vegetation seen in photos predominantly undesirable weedy plant species.



**Photo 2:** Photo taken from the well location, facing north. See comments under photo 1.



Inspection Photos  
Operator: FOUNTAINHEAD RESOURCES LTD - 30658  
Location ID: 322701



**Photo 3:** Photo taken from the well location, facing west. See comments under photo 1.



**Photo 4:** Photo taken from the well location. Photo shows gravel remains on location. This should have been removed during reclamation.