

Inspection Photos

11/20/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 318970

Inspection Doc. Number: 682502891

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the former battery location, facing southeast. Previous inspections required operator to perform additional reclamation at the battery location. Unable to find evidence that additional work has been conducted per the corrective action.



Photo 2: Photo taken from the former battery location, facing south. Previous inspections required operator to perform additional reclamation at the battery location. Unable to find evidence that additional work has been conducted per the corrective action.