

Inspection Photos

11/20/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 323368

Inspection Doc. Number: 682502893

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from access road facing north. Photo shows access road has been re-contoured and re-graded. Corrective action also required re-vegetation activities to be conducted. Unable to find evidence that access road had been seeded.