

Inspection Photos

11/20/2017

Operator: PDC ENERGY INC - 69175

Location ID: 323128

Inspection Doc. Number: 682502897

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: PDC ENERGY INC - 69175
Location ID: 323128



Photo 1: Photo taken from the northeast corner of the former battery location, facing west. Photo shows battery location has not been reclaimed and returned to crop land



Photo 2: Photo taken from the northeast corner of the former battery location, facing south. Photo shows battery location has not been reclaimed and returned to crop land



Photo 3: 2014 aerial imagery. Photo shows well and battery location prior to plugging and abandonment.



Photo 4: 1984 USGS Aerial imagery. Well was SPUD in 1985. Photo shows areas un-reclaimed at the former battery location did not pre-exist the oil and gas disturbance.