

**Inspection Photos**  
**Location Name: Grand 1**  
**API: 05-001-08118**



**Wellhead**



**Battery**

Inspection Photos  
Location Name: Grand 1  
API: 05-001-08118



**Wellhead**



**Produced water tank detail, Corrective Action: Netting on open tanks inadequate. Wildlife protections devices not adequate.**