

Inspection Photos
Location Name: Robidoux 22-13
API: 05-081-06973



Photo 1. 1 – 3” steel riser not LOTO.



Photo 2. Overview of location taken at east side facing west.