

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

11/16/2017

Submitted Date:

11/17/2017

Document Number:

689400663**FIELD INSPECTION FORM**

Loc ID 336046	Inspector Name: CONKLIN, CURTIS	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
<b>Operator Information:</b> OGCC Operator Number: <u>16700</u> Name of Operator: <u>CHEVRON USA INC</u> Address: <u>6301 DEAUVILLE BLVD</u> City: <u>MIDLAND</u> State: <u>TX</u> Zip: <u>79706</u>				<b>Findings:</b> <u>29</u> Number of Comments <u>2</u> Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Haub, Mike	(970) 697-8385	MHaub@chevron.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
52	WELL	PR	10/24/2013	GW	045-15422	SKR 598-25-BV-13	PR
53	WELL	TA	06/12/2013	GW	045-15423	SKINNER RIDGE 598-25-BV 14	TA
55	WELL	PR	10/24/2013	GW	045-15424	SKR 598-25-BV-15	PR
56	WELL	PR	10/09/2013	GW	045-15425	SKR 598-25-BV-16	PR
58	WELL	PR	02/01/2011	GW	045-15426	SKR 598-25-BV-17	PR
59	WELL	PR	10/04/2013	GW	045-15427	SKR 598-25-BV-18	PR
60	WELL	PR	03/19/2010	GW	045-15428	SKR 598-25-BV-19	PR
61	WELL	PR	10/24/2013	GW	045-15429	SKR 598-25-BV-22	PR
62	WELL	PR	10/09/2013	GW	045-15430	SKR 598-25-BV-21	PR
63	WELL	PR	04/12/2008	GW	045-15431	SKR 598-25-BV-20	PR
276276	WELL	PR	05/22/2012	GW	045-10435	SKINNER RIDGE 598-25-1	PR
294147	WELL	PR	10/28/2013	GW	045-15274	SKR 598-25-BV-03	PR
294148	WELL	PR	10/15/2013	GW	045-15275	SKR 598-25BV-04	PR
294149	WELL	PR	10/14/2013	GW	045-15276	SKR 598-25-BV-02	PR
294150	WELL	PR	01/16/2015	GW	045-15277	SKR 598-25-BV-01	PR
294151	WELL	PR	12/01/2014	GW	045-15278	SKR 598-25-BV-06	PR
294161	WELL	PR	02/01/2011	GW	045-15288	SKR 598-25-BV-05	PR
294363	WELL	PR	02/01/2011	GW	045-15400	SKR 598-25-BV-10	PR
294364	WELL	PR	10/24/2013	GW	045-15401	SKR 598-25-BV-09	PR
294365	WELL	PR	10/15/2013	GW	045-15402	SKR 598-25-BV-08	PR
294366	WELL	PR	10/28/2013	GW	045-15403	SKR 598-25-BV-07	PR
294367	WELL	PR	10/09/2013	GW	045-15404	SKR 598-25-BV-12	PR
294368	WELL	PR	02/01/2011	GW	045-15405	SKR 598-25-BV-11	PR

**General Comment:**

This is a routine field inspection, any corrective actions not addressed from previous inspections are still applicable.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Sign missing at SKINNER RIDGE 598-25-BV 14. See photos		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	12/18/2017

Emergency Contact Number:	
Comment:	Emergency contact number posted. 877-257-6007
Corrective Action:	Date:

<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Unused barrel at wellhead. See photos.		
Corrective Action:	Comply with Rule 603.f .	Date:	12/18/2017

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

<b>Equipment:</b>			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:	Bulk separator		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities				
Facility ID: <u>52</u>	Type: <u>WELL</u>	API Number: <u>045-15422</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<b><u>Producing Well</u></b>				
Comment: <u>Plunger</u>				
Corrective Action: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>			Date: <div style="border: 1px solid black; width: 100px; height: 20px;"></div>	
Facility ID: <u>53</u>	Type: <u>WELL</u>	API Number: <u>045-15423</u>	Status: <u>TA</u>	Insp. Status: <u>TA</u>
<b><u>Idle Well</u></b>				
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned      Reminder: <div style="border: 1px solid black; width: 150px; height: 15px;"></div>				
Comment: <u>Annual Form 4 Doc#401400409 in process for continued TA status. Last MIT was 6/6/13</u>				
Corrective Action: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>			Date: <div style="border: 1px solid black; width: 100px; height: 20px;"></div>	
Facility ID: <u>55</u>	Type: <u>WELL</u>	API Number: <u>045-15424</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<b><u>Producing Well</u></b>				
Comment: <u>Plunger</u>				
Corrective Action: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>			Date: <div style="border: 1px solid black; width: 100px; height: 20px;"></div>	
Facility ID: <u>56</u>	Type: <u>WELL</u>	API Number: <u>045-15425</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<b><u>Producing Well</u></b>				
Comment: <u>Plunger</u>				
Corrective Action: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>			Date: <div style="border: 1px solid black; width: 100px; height: 20px;"></div>	
Facility ID: <u>58</u>	Type: <u>WELL</u>	API Number: <u>045-15426</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<b><u>Producing Well</u></b>				
Comment: <u>Plunger</u>				
Corrective Action: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>			Date: <div style="border: 1px solid black; width: 100px; height: 20px;"></div>	
Facility ID: <u>59</u>	Type: <u>WELL</u>	API Number: <u>045-15427</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<b><u>Producing Well</u></b>				
Comment: <u>Plunger</u>				
Corrective Action: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>			Date: <div style="border: 1px solid black; width: 100px; height: 20px;"></div>	
Facility ID: <u>60</u>	Type: <u>WELL</u>	API Number: <u>045-15428</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<b><u>Producing Well</u></b>				
Comment: <u>Plunger</u>				
Corrective Action: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>			Date: <div style="border: 1px solid black; width: 100px; height: 20px;"></div>	
Facility ID: <u>61</u>	Type: <u>WELL</u>	API Number: <u>045-15429</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<b><u>Producing Well</u></b>				
Comment: <u>Plunger</u>				
Corrective Action: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>			Date: <div style="border: 1px solid black; width: 100px; height: 20px;"></div>	

<b><u>Producing Well</u></b>				
Comment:	Plunger			
Corrective Action:			Date:	
Facility ID: 62 Type: WELL API Number: 045-15430 Status: PR Insp. Status: PR				
<b><u>Producing Well</u></b>				
Comment:	Plunger			
Corrective Action:			Date:	
Facility ID: 63 Type: WELL API Number: 045-15431 Status: PR Insp. Status: PR				
<b><u>Producing Well</u></b>				
Comment:	Plunger			
Corrective Action:			Date:	
Facility ID: 276276 Type: WELL API Number: 045-10435 Status: PR Insp. Status: PR				
<b><u>Producing Well</u></b>				
Comment:	Plunger			
Corrective Action:			Date:	
Facility ID: 294147 Type: WELL API Number: 045-15274 Status: PR Insp. Status: PR				
<b><u>Producing Well</u></b>				
Comment:	Plunger			
Corrective Action:			Date:	
Facility ID: 294148 Type: WELL API Number: 045-15275 Status: PR Insp. Status: PR				
<b><u>Producing Well</u></b>				
Comment:	Plunger			
Corrective Action:			Date:	
Facility ID: 294149 Type: WELL API Number: 045-15276 Status: PR Insp. Status: PR				
<b><u>Producing Well</u></b>				
Comment:	Plunger			
Corrective Action:			Date:	
Facility ID: 294150 Type: WELL API Number: 045-15277 Status: PR Insp. Status: PR				
<b><u>Producing Well</u></b>				
Comment:	Plunger			
Corrective Action:			Date:	
Facility ID: 294151 Type: WELL API Number: 045-15278 Status: PR Insp. Status: PR				

<u>Producing Well</u>			
Comment:	Plunger		
Corrective Action:		Date:	
Facility ID: 294161 Type: WELL API Number: 045-15288 Status: PR Insp. Status: PR			
<u>Producing Well</u>			
Comment:	Plunger		
Corrective Action:		Date:	
Facility ID: 294363 Type: WELL API Number: 045-15400 Status: PR Insp. Status: PR			
<u>Producing Well</u>			
Comment:	Plunger		
Corrective Action:		Date:	
Facility ID: 294364 Type: WELL API Number: 045-15401 Status: PR Insp. Status: PR			
<u>Producing Well</u>			
Comment:	Plunger		
Corrective Action:		Date:	
Facility ID: 294365 Type: WELL API Number: 045-15402 Status: PR Insp. Status: PR			
<u>Producing Well</u>			
Comment:	Plunger		
Corrective Action:		Date:	
Facility ID: 294366 Type: WELL API Number: 045-15403 Status: PR Insp. Status: PR			
<u>Producing Well</u>			
Comment:	Plunger		
Corrective Action:		Date:	
Facility ID: 294367 Type: WELL API Number: 045-15404 Status: PR Insp. Status: PR			
<u>Producing Well</u>			
Comment:	Plunger		
Corrective Action:		Date:	
Facility ID: 294368 Type: WELL API Number: 045-15405 Status: PR Insp. Status: PR			
<u>Producing Well</u>			
Comment:	Plunger		
Corrective Action:		Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Berms	Pass	Check Dams	Pass			
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401463107	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4305059">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4305059</a>
689400664	SKR-598-25-BV	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4305056">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4305056</a>