

Augustus Energy Resources LLC, Schobe 23-04
125-11004

Inspection #688300668

11/17/2017

Routine Inspection

AUGUSTUS ENERGY RESOURCES, LLC

SCHOBE 23-4

NWNW SEC 23-T1S-R44W
RD 27 & EE, S 1/4, E INTO
YUMA COUNTY, CO

IN CASE OF EMERGENCY CALL: 970-332-3585 OR 911

11.17.2017



11.17.2017



AUGUSTUS ENERGY RESOURCES, LLC
SCHOBE 23-4
NWNW SEC 23-T1S-R44W
RD 27 & EE, S 1/4, E INTO
YUMA COUNTY, CO
IN CASE OF EMERGENCY CALL: 970-332-3585 OR 911

11.17.2017

AUGUSTUS ENERGY RESOURCES, LLC

SCHOB 23-4
NWNW SEC 23-T1S-R44W
RD 27 & EE, S 1/4, E INTO
YUMA COUNTY, CO

IN CASE OF EMERGENCY CALL: 970-332-3585 OR 911

11.17.2017

A photograph of an industrial site. In the foreground, a white sign with black text is mounted on a black metal frame. The sign contains the name of a company, a well identifier, location details, and emergency contact information. Behind the sign, a complex network of white PVC pipes is connected to a tan-colored metal structure. The ground is dry and gravelly, and a metal fence is visible in the background.

AUGUSTUS ENERGY RESOURCES, LLC

SCHOBÉ #23-03
NE/NW SEC.3-T1S-R44W
YUMA COUNTY, CO.
IN CASE OF EMERGENCY CALL: 970-332-3585 OR 911

11.17.2017



11.17.2017