

Final Reclamation Inspection

November 22, 2017

Operator: PETROSHARE CORPORATION- 10454

Location ID: 319769

Adams County, CO

NENE Section 28 T1S R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: TSUZUKI #1

Location ID: 319769




Photo 1. Google Earth aerial imagery taken 10/9/2015 illustrating the well and battery location, and access road during operations. There is no current aerial imagery available; however, all the equipment shown in the above image has all been removed. Appears the adjacent lands to the north are cropland and currently appear to be planted with winter wheat.

Inspection Photos
Location Name: TSUZUKI #1
Location ID: 319769



Photo 2. Photo taken from the southwest well/battery location, facing East. Operator has not reclaimed the well/battery location and access road per Rule 1004 standards.



Photo 3. Photo taken from the south well/battery location, facing North. See comments under Photo 2.

Inspection Photos
Location Name: TSUZUKI #1
Location ID: 319769



Photo 4. Photo taken from the north well/battery location, facing North. See comments under Photo 2.



Photo 5. Photo taken from a portion of the access road, facing North. See comments under Photo 2.