

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/28/2017

Submitted Date:

11/28/2017

Document Number:

680705059

**FIELD INSPECTION FORM**

Loc ID 424475 Inspector Name: Peterson, Tom On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10311  
Name of Operator: SRC ENERGY INC  
Address: 1675 BROADWAY SUITE 2600  
City: DENVER State: CO Zip: 80202

**Findings:**

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Pennington, David		dpennington@srcenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
424478	WELL	PR	03/01/2017	OW	123-34054	Klein 43-8D	PA

**General Comment:**

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	DRILLING/RECOMP		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 2		
Comment:	1-2" and 1-1" steel risers		
Corrective Action:		Date:	

<b>Venting:</b>		
Yes/No		
Comment:		
Corrective Action:		Date:

<b>Flaring:</b>		
Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 424478 Type: WELL API Number: 123-34054 Status: PR Insp. Status: PA

**Cement**

Cement Contractor

Contractor Name: Ranger Energy Contractor Phone: \_\_\_\_\_

Surface Casing

Cement Volume (sx): \_\_\_\_\_ Circulate to Surface: \_\_\_\_\_  
 Cement Fall Back: \_\_\_\_\_ Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_ Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_ Good Return During Job: \_\_\_\_\_

Plugging Operations

Depth Plugs(feet range): 7517'-6925' Cement Volume (sx): 45 sxs

Good Return During Job: YES Cement Type: Class G Neat 15.8#

Comment: CIBP set @ 7517' KB, TIH with tbg to 7512' KB, condition wellbore with rig pump, MIRU Ranger Energy Services cementers, hold safety meeting, establish circulation, mix and pump 45 sxs Class G Neat 15.8 ppg cement slurry balance plug (9.2 bbls total), displace tbg with 26 bbls of fresh water, RDMO cementers, POOH with tbg, ND BOP, ND WH, spear and unland csg, NU WH, NU BOP, SIW, SDFN.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Comment: Bradenhead valve is exposed at surface.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680705060	Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4312033">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4312033</a>