

| <i>Scientific Name</i> | <i>Common Name</i> | Lively 34-09 | |
|--|----------------------|---------------------|------------|
| | | <i>Adjacent</i> | <i>Pad</i> |
| NATIVE ANNUAL & BIENNIAL FORBS | | | |
| Descurainia pinnata | western tansymustard | | 2 |
| Subtotal | | 0 | 2 |
| NATIVE ANNUAL GRASSES | | | |
| Vulpia octoflora | sixweeks fescue | 4 | |
| Subtotal | | 4 | 0 |
| NATIVE & ACCEPTABLE PERENNIAL FORBS | | | |
| Sphaeralcea coccinea | scarlet globemallow | 1 | 1 |
| Subtotal | | 1 | 1 |
| NATIVE & ACCEPTABLE PERENNIAL GRASSES | | | |
| Aristida purpurea | purple threeawn | | 1 |
| Bouteloua dactyloides | buffalograss | 1 | 1 |
| Bouteloua gracilis | blue grama | 32 | 9 |
| Pascopyrum smithii | western wheatgrass | 3 | 15 |
| Sporobolus cryptandrus | sand dropseed | | 2 |
| Subtotal | | 36 | 28 |
| NATIVE SUBSHRUBS | | | |
| Gutierrezia sarothrae | broom snakeweed | | 3 |
| Subtotal | | 0 | 3 |
| NATIVE SHRUBS #N/A | | | |
| Tetradymia canescens | spineless horsebrush | p | |
| Subtotal | | 0 | 0 |
| SUCCULENT | | | |
| Echinocereus sp. | hedgehog cactus | 1 | |
| Subtotal | | 1 | 0 |
| Total Vegetation Cover | | 42 | 34 |
| Total Acceptable Cover | | 42 | 34 |
| Litter | | 19 | 21 |
| Rock | | | |
| Total Ground Cover | | 61 | 55 |
| Bare Ground | | 39 | 45 |
| Total Hits | | 100 | 100 |
| Total Species | | 8 | 9 |

| | |
|--------------------------|------------|
| Reclamation Pass? | Yes |
|--------------------------|------------|

Petroglyph Energy 2017 Well Pad Monitoring Report

Lively 34-09

North Photo



South Photo



West Photo



East Photo



Well Pad Transect



Adjacent Transect



Lively 34-09

Additional Photos

Access road east end

