

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/30/2017

Submitted Date:

11/30/2017

Document Number:

677400136**FIELD INSPECTION FORM**Loc ID 407142 Inspector Name: MONTOYA, JOHN On-Site Inspection ☐ 2A Doc Num: _____**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Operator Information:OGCC Operator Number: 67305Name of Operator: PATINA OIL & GAS CORPORATIONAddress: 1625 BROADWAY STE 2000City: DENVER State: CO Zip: 80202**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	ALL INSPECTIONS
Burn, Diana		diana.burn@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242366	WELL	PA	04/15/1997	GW	123-10157	GOETZ 1	PA

General Comment:

Location**Lease Road:**

Type	Main		
comment:			
Corrective ActionL		Date:	

Overall Good: ☒**Emergency Contact Number:**

Comment:		Date:	
Corrective Action:			

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 242366 Type: WELL API Number: 123-10157 Status: PA Insp. Status: PA

CementCement ContractorContractor Name: Robert AmenContractor Phone: 970-867-2432Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____

Cement Volume (sx): _____

Good Return During Job: _____

Cement Type: _____

Comment: RIH TO 6900', 220 JTS, SET RETAINER AT 6900' AND SNFN
RE-ENTRY COMPANY MAN ROBERT AMEN

Corrective Action: RIH TO

Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
677400137	rig and circutating tanks	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4314362