

## Inspection Photos

Location Name: Wickstrom #6-12

API: 05-123-32065

Inspection Date: November 28, 2017



**Photo #1 – View of wellhead, unused separator and well sign, looking south.**



**Photo #2 – Uncapped, 1" flowline riser leading from separator to wellhead alongside tagged-out and bullplugged 2" riser west of wellhead.**

Location Name: Wickstrom #6-12

API: 05-123-32065

Inspection Date: November 28, 2017



Photo #3 – 1" flowline riser and accumulation of wind-blown weeds on east side of separator.

