

Inspection Photos
Location Name: Simpson FD Pad
Location ID: 440858
Inspection Date: 11-30-2017



**Wellheads looking northwest with flares northwest of them.
Stained soil around wellheads (10:44)**



Wellheads looking west (10:44)

Inspection Photos
Location Name: Simpson FD Pad
Location ID: 440858
Inspection Date: 11-30-2017



Trash around wellheads needs cleaned up (10:51)



Unused equipment at wellheads needs to be picked up (10:53)

Inspection Photos

Location Name: Simpson FD Pad

Location ID: 440858

Inspection Date: 11-30-2017



(#1)Unused/unmarked 2" steel riser at compressors (11:15)



(#2)Unused/unmarked 2" steel riser at compressors (11:15)



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Simpson FD Pad

Location ID: 440858

Inspection Date: 11-30-2017



(#3)Unused/unmarked steel riser at compressors (11:17)



1" unused/unmarked steel riser and 2-2" steel marked/unused risers east of separators (11:20)



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Simpson FD Pad

Location ID: 440858

Inspection Date: 11-30-2017



2-1" unused/unmarked steel risers, 1-2" unused/unmarked steel riser, 2-2" marked/unused steel risers west of separators (11:24)



Battery sign looking west. No emergency contact information (11:26)



Inspection Photos

Location Name: Simpson FD Pad

Location ID: 440858

Inspection Date: 11-30-2017



Stained soil around crude oil tanks (11:29)



Stained soil at drain line on crude oil tank (11:32)



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Simpson FD Pad

Location ID: 440858

Inspection Date: 11-30-2017



1" unused/unmarked steel riser at ECD knockout (11:32)



Stained soil under load line on crude oil tank (11:33)



Inspection Photos
Location Name: Simpson FD Pad
Location ID: 440858
Inspection Date: 11-30-2017



Stained soil around north production water tank (11:35)



Unused shed east of tank battery (11:37)

Inspection Photos

Location Name: Simpson FD Pad

Location ID: 440858

Inspection Date: 11-30-2017



**2" unused/unmarked steel riser northwest of crude oil tanks
(12:19)**



**Crew on location cleaning up stained soil around wellheads
(13:19)**



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Simpson FD Pad

Location ID: 440858

Inspection Date: 11-30-2017



**Hardline coming from Simpson FD 16-382HN wellhead west
of separators (14:10)**



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources