

Inspection Photos
Location Name: McCallum Unit 183
API: 05-057-06452



Photo 1. Overview of location taken at entrance facing northwest.



Photo 2. Stained soil at wellhead.