

Photo#1:

Overview of Location to Northeast. Arrow indicates un reclaimed Facilities; Star indicates former site of Compressor station buildings.



October 21, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Quicksilver PA Alpha State API#081-053552

Photo#2:

View from Compressor site to West, across Road at Associated facilities of Alpha State Well



October 21, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Quicksilver PA Alpha State API#081-053552

Photo#3:

Photo#4:

All debris, riser, materials have not been cleaned up off Pad area of Location



October 21, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Quicksilver PA Alpha State API#081-053552

Photo#5:

All debris, riser, materials have not been cleaned up off Pad area of Location

Photo#6:



October 21, 2017