

Location Name: McIntyre 34-16 flowline release Spill ID: 453260 Inspection Date: 12/5/2017



Photo 1 – Excavation area looking south at south sidewall.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: McIntyre 34-16 flowline release Spill ID: 453260 Inspection Date: 12/5/2017



Photo 2 – Closer image of south sidewall of excavation.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: McIntyre 34-16 flowline release Spill ID: 453260 Inspection Date: 12/5/2017



Photo 3 – Excavation looking northeast from southwest corner of excavation.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: McIntyre 34-16 flowline release Spill ID: 453260 Inspection Date: 12/5/2017



Photo 4 – Viewing toward the east at the east sidewall of excavation.

