

Inspection Photos

12/04/2017

Operator: PCR OPERATING LLC - 10657

Location ID: 313768

Inspection Doc. Number: 682502915

Morgan County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: PCR OPERATING LLC - 10657
Location ID: 313768



Photo 1: Photo taken from the southwest corner of the location. Previous inspections require operator to remove anchors from the location. Photo shows operator sign for the location (recently changed to PCR) and one of the four remaining anchors on the location. Anchors have not been removed per the CA.



Photo 2: Photo taken from the location. Photo shows pipe riser has not been removed per the CA.

Inspection Photos
Operator: PCR OPERATING LLC - 10657
Location ID: 313768



Photo 3: Photo taken from the location. Photo shows gravel remains and no additional reclamation activities have been conducted per the CA's.



Photo 4: Photo taken from the location. Photo shows gravel remains and no additional reclamation activities have been conducted per the CA's.