

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/07/2017

Submitted Date:

12/07/2017

Document Number:

681902319**FIELD INSPECTION FORM**
 Loc ID 305942 Inspector Name: HELGELAND, GARY On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:14 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCinspections@anadarko.com	All Inspections

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	SATISFACTORY		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	SATISFACTORY		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	SATISFACTORY		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: SATISFACTORY

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds at well.		
Corrective Action:	Control weeds.	Date:	12/21/2017

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	panel		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Bird Protectors	# 3		
Comment:	SATISFACTORY		
Corrective Action:		Date:	
Type: Plunger Lift	# 4		
Comment:	SATISFACTORY		
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:	SATISFACTORY		
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 2		
Comment:	SATISFACTORY		
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:	SATISFACTORY		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	BV CONCRETE		,
Comment:	Berm shared with oil tank (s).				
Corrective Action:		Date:			

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:		Date:		

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	BV CONCRETE		,
Comment:	Berm shared with oil tank (s).				
Corrective Action:		Date:			

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:		Date:		

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		40.050253,-104.725094
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	<div></div> <div>Date: </div>
Emission Control Burner (ECB): YES	
Comment:	
Pilot: ON	Wildlife Protection Devices (fired vessels): YES