

Photo#1:

Overview of Location to Southeast. Equipment & supplies, are stored on location,



November 30, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Black Hills Horseshoe Canyon Loc#312445

Photo#2:

Equipment & supplies are stored on location; view to West.



November 30, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Black Hills Horseshoe Canyon Loc#312445

Photo#3:

Sediment is migrating Across Access Road entry, along South side of Road & off Site.



Photo#4:



November 30, 2017

Photo#5:

Sediment is migrating Across Access Road entry, along South side of Road & off Site.



November 30, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Black Hills Horseshoe Canyon Loc#312445